

**APPENDIX A: Projects Under \$1000**  
Priority List

Category	Location of Barrier	Description of Barrier	Park Location	Recommendation	Priority	Year	Est. Cost	Comments
Signs	Entry	No arrow sign showing way to ADA entry and no sign marking door	CVCC	Add arrow and entry signs	1		\$100.00	<b>1127B.3</b>
Entry	Doors	door stops mounted on door bottoms	CVCC	remove door stops	1		n/a	
Entry	Doors	No 10" plate at bottom of doors both sides	CVCC	Verify heights and install proper plates	1		\$200.00	<b>1133B.2.6</b>
Entry	Rug	Loose rug at entry	CVCC	affix carpet to floors or change out linoleum tiles to carpet tiles	1		\$500.00	Federal requirements overrides California Code <b>1124B.3 4.5.3</b>
Entry	Lower ADA entry	No ADA entry sign	CVCC	Install appropriate sign	1		\$50.00	<b>1117B.5.8.1.2 &amp; 1127B.3</b>
Entry	Lower ADA entry	No exit sign	CVCC	Install appropriate sign	1		\$50.00	<b>1011B.3.1</b>
Entry	Signage	No sign at entrance to parking lot directing to parking area	CVCC	Install appropriate sign	1		\$50.00	<b>1127B 4.1.3(16)(b)</b>
Exits	Signage	No tactile exit signs	CVCC	Install tactile exit sign at all exit doors	1		\$500.00	<b>1011.3.1</b>
Exit door	End hallway	Gap between threshold and landing too wide	CVCC	install Pemko fix	1		\$500.00	
Stairs	Exterior	Stripping worn	CVCC	re-strip steps	1		\$100.00	<b>1133B.4.4 &amp; 1127B.4</b>
Bldg	Rec Bldg	No exterior ADA sign at side double doors showing ADA entrance	Recreation Park	Install signs as required	1		\$100.00	<b>1117B.5.8.1.2 &amp; 1127B.3</b>
Bldg	Rec Bldg	No interior tactile sign at ADA exit	Recreation Park	Install tactile sign at ADA exit door on right side	1		\$50.00	<b>1011.3.1</b>
Bldg	Rec Bldg	Customer service door exceeds 5# pressure	Recreation Park	Adjust or replace as necessary	1		\$500.00	<b>1133B/2/5/2 4.13.11(2)</b>
Bldg	Craft room	No tactile sign at interior exit wall	Recreation Park	Mount tactile exit sign	1		\$50.00	<b>1011.3.1</b>
Bldg	Men's Restroom	No loop handles or grab bars on ADA stall	Recreation Park	Change handles and install grab bars to code in ADA stall	1		\$100.00	<b>1115B.3.1.4.5 &amp; 1115B.3.1.4.5</b>

**APPENDIX A: Projects Under \$1000**  
Priority List

Signage	Entry	No entry sign directing to ADA facilities	Railhead Park	erect a sign directing to ADA facility	1	\$50.00	simple arrow sign at entrance directing people to restrooms and parking
Signage		ADA doors signs on restroom doors too low	Placer Hills Pool	adjust height of signs	1	\$100.00	
Signage		No entry sign directing to ADA restrooms	Placer Hills Pool	install sign at entry by ADA parking directing to restrooms	1	\$100.00	
Signage	Entry	No direction sign to ADA parking/entry	Overlook	Install standard entry directional signage	1	\$200.00	<b>1127B.3</b>
Restroom	Women's bathroom	Threshold need repair	Overlook	Repair threshold	1	\$500.00	If door width is not 32" clear, probably structural change needed\
path of travel	wood steps	no visual stripping at wood steps	Overlook	paid tread nose with visual stripping	1	\$100.00	<b>1133B.4.4 &amp; 1127B.4</b>
Signage	Park Entry	No ADA signage at entries directing people to ADA entrance	Regional Park	Erect signs at park entries directing people to ADA facilities	1	\$500.00	<b>1127B.3</b>
Gym	Courtyard	Grates within path of travel	Regional Park	Remove grates if possible so none are in path of travel	1	\$500.00	<b>1133B.7.2 4.5.4</b>
Lakeside Room	threshold	missing tactile signage at door and door pressure is too hard	Regional Park	Install signage and repair door pressure	1	\$500.00	<b>1133B.2.5.2 &amp; 3 1117B.5.8 &amp; 1127B 4.13.11(2)</b>
Gym and Lakeside Room	thresholds	carpets not ADA compliant	Regional Park	glue down carpets or install carpet tiles in side gym doors and lakeside room	1	\$500.00	<b>1133B.3 4.5.3</b>
Gym	thresholds	gym doors not ADA accessible	Regional Park	make repairs to carpets and install ADA tactile signage directing people to accessible door	1	\$500.00	
Gym	Doors	Footholds exist on all doors	Regional Park	remove all door footholds	1	n/a	
Signage	parking	signs not compliant at parking areas.	Railhead Park	add ada parking only sign at stalls	2	\$425.00	4 spaces plus 1 van accessible \$100 per stall/\$125 van accessible

**APPENDIX A: Projects Under \$1000**  
Priority List

Parking	all parking	ada parking stalls force people into drive aisle	Railhead Park	provide min. 4' path in front of stalls to restrooms	2	\$2,500.00	add 30' sidewalk and revise curb
Parking	all parking	stalls not consolidated	Railhead Park	consolidate parking stall locations and include van accessible	2	\$500.00	100 regular spaces require 4 additional ADA spaces c/ one van accessible. Materials only costs
parking	all parking	no van accessible spaces marked and signed	Railhead Park	properly mark and sign van accessible space. Min 1	2	\$150.00	
parking	all parking	stripping color not to code	Railhead Park	paint blue stripping and universal sign on spaces	2	\$200.00	
Parking	Restroom	Parking at restroom not in compliance. Need yellow domes, signage, van aisle and level stalls	Overlook	Install signs, truncated domes, level stall and hc aisle	2	\$1,000.00	needs domes full length and minimum 12" deep <b>1133B.8.5 and 1129B.3.1</b>
Parking	Parking Lot Entrance	No sign at parking lot entrances that meets code for unauthorized use and fines	CVCC	Install signs for unauthorized use and fines	2	\$75.00	<b>1129B.4 4.6.4</b>
Parking	Parking Lot	Stripping wrong color, needs to be blue	CVCC	Repaint to blue	2	\$100.00	<b>1129B.3</b>
Parking	Signage	No \$250 fine sign at parking stalls	CVCC	Install \$250 sign each stall	2	\$75.00	<b>1129B.4 4.6.4</b>
Entry	Ramp	No truncated domes at sidewalk ramp	CVCC	Install truncated domes 36" back on ramp landing	2	\$400.00	<b>1133B.8.5</b>
Entry	Steps	No yellow edge stripping on steps	CVCC	Paint step edges to meet code	2	\$100.00	<b>1133B.4 &amp; 1127B.4</b>
Parking Lot	entry ramp	remove or install truncated domes	CVCC	remove or install truncated dome	2	\$400.00	<b>1133B.8.5</b>
Parking	lower ramp	No truncated domes	CVCC	install truncated domes	2	\$500.00	<b>1133B.8.5</b>
Stairs	Exterior	no visual stripping	CVCC	Paint steps to code	2	\$100.00	<b>1133B.4.4 &amp; 1127B.4</b>
Signage	ADA Stall	signs missing at ADA stalls	Ashford	install code required signs	2	\$100.00	<b>1129B.4 4.6.4</b>
Signage	ADA Stall	Current stall sign should be located at park entry	Ashford	relocate sign to entry	2	\$50.00	<b>1127B.3 4.1.3(16)(b)</b>

**APPENDIX A: Projects Under \$1000**  
Priority List

Signage	ADA Stall	Two entry signs are at ADA stalls, only need one. Relocate second sign to another park entry	Ashford	Relocate sign to another park entry	2	\$50.00	<b>1127B.3</b> 4.1.3(16)(b)
Modulars	ramps	Missing truncated domes and sign at ramp leading to parking lot	Recreation Park	Install tactile surface and "fine" sign	2	\$600.00	<b>1133B.8.5</b>
GYm	Parking	Missing sign for \$250 fine at parking stall	Regional Park	Install required signage	2	\$100.00	<b>1129B.4</b>
Gym	Parking	Missing blue stripping at parking stalls	Regional Park	Install required blue stripping	2	\$500.00	<b>1129B.3</b>
signage	restrooms	men's and women's signs at side of door mounted too high	Railhead Park	adjust door sign heights	3	\$25.00	minor parts (no labor)
restroom	women	grab bars at side of toilet too high	Railhead Park	adjust height of grab bar	3	\$25.00	minor parts (no labor)
restroom	men	grab bars at side of toilet too high	Railhead Park	adjust height of grab bar	3	\$25.00	minor parts (no labor)
restroom	men	urinals set too high	Railhead Park	adjust urinal heights	3	\$100.00	minor parts (no labor)
restroom	men and womens	flushvalve on wall above toilet	Railhead Park	adjust flush valve location and change from push button to lever	3		no lever style available, change out fixture
restroom	men and womens	sink faucets are not compliant	Railhead Park	install new lever style faucets	3	\$300.00	
restroom	men and womens	garbage cans block clear space at doors	Railhead Park	move locations	3		
restroom	men and womens	toilet paper holders height interferes with grab bars	Railhead Park	adjust height of TP holders	3	\$25.00	minor parts (no labor)
restroom	men and womens	no door signs mounted on doors	Railhead Park	add door signs	3	\$100.00	
Restroom	Men's Restroom	grab bar behind toilet 1" too high	Placer Hills Pool	adjust height	3	\$100.00	
Restroom	Men's Restroom	paper towel holder exceeds 40" max	Placer Hills Pool	adjust height	3	\$100.00	
Restroom	Men's Restroom	flush valve on toilet on wrong side	Placer Hills Pool	change valve or replace toilet with unit with correct	3	\$500.00	

**APPENDIX A: Projects Under \$1000**  
Priority List

Restroom	Men's Restroom	Toilet paper holder too high	Placer Hills Pool	install below grab bar and minimum 19" from floor	3		\$100.00	
Restroom	Women's Restroom	Toilet centered too far from wall	Placer Hills Pool	toilet to be centered 18" from wall	3		\$500.00	
Restroom	Women's Restroom	grab bars too high	Placer Hills Pool	adjust grab bar location	3		\$100.00	
Restroom	Women's bathroom	Toilet not at correct height	Overlook	Install toilet at correct height and verify grab bars and fixtures. Adjust as necessary	3		\$1,000.00	<b>1115B.3.2.3</b>
Restroom	Women's bathroom	No loop handles on ADA stall or door closer	Overlook	Install loop door handles and closer	3		\$100.00	<b>1115B.3.1.4.5</b>
Restroom	Women's bathroom	Towel holder and soap dispenser at wrong location and height	Overlook	Correct location and height from floor	3		\$300.00	<b>1115.B.8.3</b>
Restroom	Women's bathroom	sink height needs adjustment	Overlook	Verify and correct as needed	3		\$200.00	<b>1115B.4.7.1</b>
Restroom	Men's Restroom	towel holder in wrong location	Overlook	move towel holder	3		\$200.00	<b>1115B.8.3</b>
Restroom	Men's Restroom	door closure broken	Overlook	repair/replace door closer	3		\$200.00	<b>1115B.3.1.4.4 &amp; 1133B.2.5.1 4.13.10</b>
Restroom	Men's Restroom	trash cans in path of travel	Overlook	relocate trash cans	3		n/a	
Restroom	Men's Restroom	signage missing	Overlook	add code required signs	3		\$200.00	<b>1127B.3 &amp; 1117B.5.8.1.2</b>
Restroom	Unisex Main Floor	No circular women's sign next to door	CVCC	Install appropriate sign	3		\$50.00	<b>1115B.6.2</b>
Restroom	Unisex Main Floor	Mirror height not to code	CVCC	measure and adjust	3		\$50.00	not to exceed 40" from floor
Restroom	Unisex Main Floor	No sign to point to access to bathroom	CVCC	Install appropriate sign	3		\$30.00	<b>1117B.5.8.1.3</b>
Restroom	Womens office bathroom	soap dispenser too high	CVCC	lower soap dispenser	3		\$50.00	<b>1115.B.8.3 4.23.7</b>

**APPENDIX A: Projects Under \$1000**  
Priority List

Upper Restroom	Womens	Outdated sign	CVCC	replace with current sign	3		\$75.00	Need round sign with tactile braile
Room entries	All rooms	no tactile room name entry signs	CVCC	install tactile signs at all room entrances	3		\$800.00	Page 339 <b>1117B.5.1.1</b> 4.1.2(7)
Bathroom	Women's Restroom	front door kicker	Ashford	remove	3		\$50.00	<b>1133B.2.5.2</b> illegal device to be removed
Bathroom	Men's Restroom	no visual stripping on steps	Ashford	paint visual stripping	3		\$100.00	<b>1133B.4.4 &amp; 1127B.4</b>
Bathroom	Men's Restroom	paper towel holder too high	Ashford	lower to code req'd height	3		\$100.00	<b>1115B.8.3</b>
Bathroom	Men's Restroom	urinal at wrong height	Ashford	move urinal to correct height	3		\$200.00	<b>1115B.4.2.1</b> 4.22.5
Bathroom	Men's Restroom	toilet too low	Ashford	raise to proper height and repair flush toilet	3		\$200.00	<b>1115B.3.2.3 &amp; 1115B4.1.4</b>
BLdg	Men's Restroom	Toilet wrong distance from wall	Recreation Park	Set toilet correct distance from wall, verify correct height	3		\$500.00	
Bldg	Men's Restroom	Paper hold on wrong wall, correct height	Recreation Park	Move paper hold and set at correct height	3		\$50.00	<b>1115B.8.4</b> 4.17.3
Bldg	Men's Restroom	Paper towel and mirror set to high	Recreation Park	Correct heights	3		\$75.00	
Gym	Restrooms	Bathroom signage not compliant	Regional Park	Install ADA compliant restroom signage	3		\$250.00	<b>1117B.5.7</b>
Gym	Restrooms	Footholds exist on entry doors	Regional Park	Remove footholds from all doors	3		n/a	
Gym	Women's Bathroom	Entry door has too much pressure	Regional Park	Adjust door for no more than 5# of pressure, replace mechanism	3		\$250.00	<b>1133B.2.5.2 &amp; 3</b> 4.13.11(2)
Gym	Women's Bathroom	Trash cans within path of travel blocking access	Regional Park	Relocate trash cans	3		n/a	
Gym	Womens Bathroom	No loop handles on ADA stall door	Regional Park	Install loop handles on ADA stall door, both sides	3		\$100.00	<b>1115B.3.1.4.5</b>
Gym	Womens Bathroom	grab bar behind toilet too short	Regional Park	install proper length grab bar	3		\$200.00	<b>1115B.4.1.4</b> 4.16.5

**APPENDIX A: Projects Under \$1000**  
Priority List

Gym	Womens Bathroom	Flush valve on wrong side of toilet	Regional Park	replace toilet unit with proper flush valve	3		\$800.00	<b>1115B.4.1.4 4.16.5 4.16.5</b>
Gym	Womens Bathroom	Toilet paper holder in wrong location	Regional Park	Move to other side of toilet at proper height	3		\$75.00	<b>1115B.8.4 4.17.3</b>
Gym	Women's Bathroom	Shower door needs closure device	Regional Park	Install ADA compliant door closure device	3		\$250.00	<b>1133B.2.5 4.13.11(2)(b)</b>
Gym	Men's Bathroom	Entry door too heavy, needs self closure device	Regional Park	Replace door and install closure device	3		\$250.00	
Gym	Men's Bathroom	No loop handles on ADA stall door	Regional Park	install loop handles on ADA stall door, both sides	3		\$100.00	<b>1115.B.3.1.4.5</b>
Gym	Men's Bathroom	gap in pavement outside entry door	Regional Park	repair gap in pavement	3		\$250.00	
Gym	Men's Bathroom	Toilet paper holder in wrong location	Regional Park	Move toilet paper holder to correct side and height	3		\$100.00	<b>1115B4.1 &amp; 1115B.8.4 4.22.4 , 4.2.3.4 , 4.16.6</b>
Restrooms	Women's at Shop	No loop handles on ADA stall door	Regional Park	install loop handles on ADA stall door	3		\$100.00	<b>1115B.3.1.4.5</b>
Restrooms	Women's at Shop	flush valve on wrong side of toilet	Regional Park	move flush valve	3		\$500.00	<b>1115B.4.1.4 4.16.5</b>
Restrooms	Women's at Shop	no ADA door closer	Regional Park	install ADA door closer	3		\$100.00	<b>1115B.3.1.4.4</b>
Restrooms	Women's at Shop	garbage cans blocks path of travel	Regional Park	move garbage cans	3		n/a	
Restrooms	Men's At Shop	garbage cans blocks path of travel	Regional Park	garbage cans blocks path	3		n/a	
Restrooms	Men's At Shop	urinal may be too low	Regional Park	verify and correct	3		\$500.00	<b>1115B.4.2.1 4.22.5, 4.18.2</b>
restroom	men and womens	drinking fountain not compliant	Railhead Park	install new bi-level drinking fountain	4		\$1,800.00	
Utility	Sierra Room	pull down cord on screen not long enough	CVCC	install proper length cord	4		\$50.00	
Stairs	Interior stairwell	No visual stripping	CVCC	install stripping (alternate carpet?)	4		\$1,000.00	<b>1133B.4.4</b>
Doors	Door closers	door closers need to be checked	CVCC	check and adjust as needed	4		n/a	<b>1133B.2.5</b>

**APPENDIX A: Projects Under \$1000**  
Priority List

Rooms	chalkboards	verify heights, may be too high	CVCC	adjust heights to 40" max from floor	4	\$100.00	same as for mirrors etc.
site furnishings	shelter	# of picnic tables may not be adequate	Ashford	verify req'd # of tables and install ADA table(s)	4	\$800.00	<b>1132B.3.1</b> 1 per 20
Bldg	Kitchen	Door knob should be lever type	Recreation Park	Change door knob to lever type	4	\$150.00	Kitchen considered commercial. Need to upgrade features to meet that standard <b>1133B.2.5.2</b>
Pool Area	Pool Deck	No wheelchair designated spot on pool deck	Recreation Park	Mark and sign designated wheelchair location on pool deck	4	\$100.00	Reasonable accomodation for path of travel may prohibit completing this item <b>1104B.4.1</b>
Entry	Bluebird Room	Threshold not to code	CVCC	revise threshold if possible	5	\$300.00	<b>1133B.2.4.1</b> 4.13.8
Begg's Field	Concrete steps	no visual stripping on concrete steps	Recreation Park	paint steps with yellow strip	5	\$100.00	<b>1127B.4 &amp; 1133B.4.4</b>
Bldg	Women's Restroom	Pipes under sink not insulated as req'd by code	Recreation Park	Install code compliant insulation	7	\$400.00	<b>1115.B.4.7.1&amp;2</b> 4.24.6
Bldg	Women's Restroom	Mirror bottom exceeds maximum 40" from floor	Recreation Park	Relocate mirror to no greater than 40" from floor	7	\$100.00	
Bldg	Women's Restroom	ADA door missing loop handles on both sides of door	Recreation Park	Install loop handles on both sides of ADA stall	7	\$100.00	<b>1115B.3.1.4.5 &amp; 1115B.3.1.4.5</b>
Bldg	Women's Restroom	ADA stall door missing 3 second closing device	Recreation Park	Install 3 second closing device on ADA stall door	7	\$200.00	<b>1133B.2.5 &amp; 1115B.3.1.4.4</b> 4.13.10
Bldg	Women's Restroom	Grab bars missing in ADA stall	Recreation Park	Install ADA grab bars	7	\$200.00	<b>B1115B3.1.5, 1115B.4.1.3</b> 4.22.4 4.23.4
Bldg	Men and Women's Restroom	Paper seat cover dispenser location does not meet code requirements	Recreation Park	Change paper dispenser to meet code requirements	7	\$100.00	
Restroom	Picnic Area	No ADA table	Placer Hills Pool	Need one ADA table	8	\$900.00	
path of travel	ramp at skatepark	landing too short	Overlook	remodel landing to 72"	8	\$1,000.00	<b>1133B.5.4.6</b>
door	card room	refrigerator in clear way	CVCC	remove refridgerator	8		need 5' clearance all sides

**APPENDIX A: Projects Under \$1000  
Priority List**

card room	sink	too high	CVCC	revise when remodel	8			<b>1115B.4.3.2 4.19.2</b>	
card room	closet	rod too high	CVCC	revise to 48" high	8		\$50.00		
Kitchen	stove	main kitchen stove not accessible	CVCC	relocate to meet code	8		n/a	done at kitchen future remodel	
kitchen	sink	kick plate violates code	CVCC	remodel to remove kick plate	8		\$500.00		
Bldg	Women's Restroom	Countertop 1/2" too high at 34-1/2"	Recreation Park	Remodel countertop to meet maximum 34" height	8		\$500.00	<b>1122B.4 4.32.4</b>	
Begg's Field	Bleachers	No "family" bench to prevent isolation fine	Recreation Park	Install bench adjacent to ADA observation location	8		\$500.00	remove existing elevated bench, it restricts viewing area <b>1104B.3.5 4.33.3</b>	
Gym	Vending Machine	vending maching alcove approach too steep.	Regional Park	If this is to be used for vending machines, then alcove pitch will have to be corrected	8		n/a	No vending machines currently are used here	
<b>Estimated Costs</b>								<b>\$33,630.00</b>	
<b>20% Contingency</b>								<b>\$6,726.00</b>	
<b>Total Project Costs</b>								<b>\$40,356.00</b>	